

VEHICLE INSPECTION REPORT

VX16AEE

Dennis Elite 6

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 04/04/2016

Colour WHITE

Gearbox AUTOMATIC

Year 2016

VIN SEG2628HR6BG21599

Axle Combi 6x2

Mileage 83,889 Km Warranted

Body Style Refuse Collector

Rear Suspension Steel

Fuel Type Diesel

Cab Type CREW CAB

WARNING LIGHT ON DASH OLYMPUS TP22 BODY, TERBERG SPLIT LIFT

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Broken
Replace



2: Bonnet
Scratched
UpTo 25mm Thru Paint



3: Bumper Front
Cracked
Over 25mm



4: Number Plate Front
Broken
Replace



5: Bumper Front Moulding
Broken
Replace



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Handle Outer nsf
Broken
Replace



8: Other
N/A
N/A



9: Other
N/A
N/A



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Other
N/A
N/A



13: Other
N/A
N/A



14: Other
N/A
N/A



15: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



16: Other
N/A
N/A



17: Seat Base Cover nsf
Torn
Over 3mm



18: Seat Base Cover nsf
Holed
Over 3mm



19: Seat Base Cover nsf
Holed
Over 3mm



20: Fascia Panel
Broken
Replace



21: Other
N/A
N/A



22: Seat Base Cover osf
Holed
Over 3mm



23: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Average	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK