

VEHICLE INSPECTION REPORT

GF63SKJ

Ford Transit 2.2

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Bedford

Reg. date 01/01/2013

Year 2013

Mileage 196,570 Km Not Warranted

Fuel Type DIESEL

GVW 4100kg

Colour WHITE

VIN WF0DXXTTFDDA26297

Body Style Minibus

MOT Due 30/01/2027

Gearbox MANUAL

16 SEATS PLUS DRIVER, SIDE LOADING DOOR

Tyres

NSF

NSR

OSF

OSR

Spare






Features

• Air conditioning


• Front electric windows

Photos






Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
Over 10mm




4: Roof
Rusted
Over 5mm



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage



10: Qtr Panel osr
Scratched
UpTo 25mm Not Thru Paint



11: Qtr Panel osr
Dented
With Paint Damage



12: Sill os
Scratched
Over 25mm Thru Paint



13: B Post os
Rusted
Over 5mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK